

Product Safety Recall



Trojan Park Leg Trailer Electric Stand Model 307007

Sold by Supercheap Auto, Repco and other automotive and trailer supply stores from 1 April 2009 to 1 May 2020

Defect: A gasket in the parking leg contains chrysotile asbestos.

Hazard: The trailer leg contains a gasket containing chrysotile asbestos.

If asbestos fibres are released into the air and breathed in, they can cause serious medical conditions, including asbestosis, lung cancer and mesothelioma.

What to do: Consumers with the affected trailer leg should contact AutoPacific to register their details so their remedy can be arranged.

- Consumers may continue to operate and use the Parking leg as normal until their remedy is available.
- Consumers must not disassemble or open the casing.
- Consumers should be aware that improper disposal of materials containing asbestos is an offence.

Where details are available, AutoPacific will also contact affected consumers directly to provide further advice.

Contact details: For further information, contact AutoPacific by phone on 03 9701 9500, email at dmalone@autopacgroup.com.au or via the website at https://autopacificgroup.com/#CONTACT_US

**See productsafety.gov.au for
Australian product recall information**